## Message Text

UNCLASSIFIED

PAGE 01 DACCA 00847 190443Z

22

ACTION ST-01

INFO OCT-01 ISO-00 PASS-00 /002 W

----- 015396

R 190300Z FEB 76 FM AMEMBASSY DACCA TO SECSTATE WASHDC 9734

**UNCLAS DACCA 0847** 

E.O. 11652: N/A

TAGS : ASUP, BG

SUBJECT: MALFUNCTIONING VEHICLE PARTS

PLEASE PASS TO: ENGINEERING AND SALES DEPTS., I.H. EXPORT CORPN., 401 NORTH MICHIGAN AVENUE, CHICAGO, ILLINOIS, 60611.

- 1. THIS POST HAS A SMALL BUT GROWING FLEET OF I.H. SCOUT II VEHICES EQUIPPED WITH V8-304 ENGINES/STANDARD TRANSMISSION. AT PRESENT, TWO OF THESE SCOUTS (SER NOS. E0062-EGD-29102 AND 14333) EACH WITH APPROXIMATELY 3,500 ACCURMULATED MILES, ARE HAVING IGNITION PROBLEMS: WHEN DRIVING WITH EITHER COLD OR WARM (NORMAL) ENGINE TEMPERATURE, A TOTAL LOSS OF IGNITION OCCURS, VEHICLE STALLS AND CANNOT BE RESTARTED. HAVE TENTATIVELY IDENTIFIED SOURCE OF PROBLEM TO BE THE "ELECTRONIC IGNITION CONTROL" (MOUNTED ON FIREWALL-PART #451565C2) WHERE WE'VE DISCOVERED THAT A SHARP LIGHT BLOW FROM A HAMMER, ROCK, WRENCH OR SHATEVER ELSE IS AVAILABLE REINSTATES SYSTEM'S ABILITY TO PROVIDE IGN THIS IS NOT AN ACCEPTABLE SOLUTION AND UNTIL VEHICLES ARE OPERATING IN ACCEPTABLE MANNER, THEY CANNOT BE UTILIZED FOR PURPOSE FOR WHICH BOUGHT.
- AS TWO VEHICLES EXPERIENCING IDENTICAL PROBLEM, POSSIBILITY OF OTHERS BEING AFFECTED IS NOT REMOTE.
- 3. I.H. REPRESENTATIVE DACCA UNABLE TO ASSIST.
- 4. BEST SOLUTION WOULD BE FOR YOU TO SHIP VIA AIR FREIGHT TO DACCA TWO REPLACEMENT ELECTRONIC IGNITION CONTROL UNITS FOR THESE VEHICLES. WE IN TURN WILL SHIP DEFECTIVE ITEMS TO YOUR ENGINEE-UNCLASSIFIED

UNCLASSIFIED

PAGE 02 DACCA 00847 190443Z

RING (ADVISE ADDRESS) DEPT. FOR EVALUATION.

- 5. THESE VEHICLES ARE VITAL TO SUSTAINED MISSION OPERATIONS AND MOST EXPEDITIOUS CORRECTION OF THIS PROBLEM IS ESSENTIAL AT THE EARLIEST POSSIBLE DATE. ALL ASSISTANCE WILL BE MUCH APPPRECIATED.
- 6. PLEASE ADDRESS RETURN CORRESPONDENCE TO HORN, GSO OFFICE, AMERICAN EMBASSY, DACCA, BANGLADESH. BOSTER

NOTE BY OC/T: PASSED TO ABOVE ADDRESSEE.

UNCLASSIFIED

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 19 FEB 1976 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Decument Number: 107600000

Document Number: 1976DACCA00847
Document Source: CORE
Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D760062-0083

From: DACCA

Handling Restrictions: n/a

Image Path:

Legacy Key: link1976/newtext/t19760236/aaaabfaw.tel Line Count: 71 Locator: TEXT ON-LINE, ON MICROFILM

Office: ACTION ST Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a
Previous Classification: n/a Previous Handling Restrictions: n/a Reference: n/a Review Action: RELEASED, APPROVED
Review Authority: ullricre

Review Comment: n/a Review Content Flags:

Review Date: 21 JUL 2004 **Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <21 JUL 2004 by oatisao>; APPROVED <27 AUG 2004 by ullricre>

**Review Markings:** 

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MÁY 2006

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: : MALFUNCTIONING VEHICLE PARTS PLEASE PASS TO: ENGINEERING AND SALES DEPTS., I.H. EXPORT CORPN. TAGS: ASUP, BG
To: STATE

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006